



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO3790

Work Order Type: Weatherization

Audit Name: 14014SO3790

CLIENT INFORMATION

Client Name:

Client ID: 14014SO3790

Alt. Client ID: BEDFORD

Address: , Unit 1179

BELL BUCKLE, TN 37020

AGENCY INFORMATION

Agency: South Central Human Resource Agency

Address: (PO Box 638) 1437 Winchester Highway
Fayetteville, TN 37334

Agency Phone: (931) 433-7182

Fax: (931) 433-0074

Email Address:

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

Client Name:

Client ID: 14014SO3790

Alt. Client ID: BEDFORD

Work Order (Bid Form)

Work Order Name: 14014SO3790

Report Run On: 10/6/2011

DOE Weatherization Assistant

Version 8.6.0

Page 1 of 5

Measures

Measure 1 General Air Sealing

Components

Inspected

Comment

SEAL ALL PLUMBING AND ELECTRICAL USE BLOWER DOOR TO REACH TARGET OF 2350 REPAIR DUCT WORK AS NEEDED SEAL REGISTERS AND DUCTS WITH MASTIC SEAL RETURN AND RETURN BOX WITH MASTIC HOME HAS HIGH READINGS NEED TO READ 1.0 OR LESS INSTALL FRONT DOOR UNIT WITH S/D WALL REPAIR WILL BE REQUIRED BEFORE INSTALLING UNIT INSTALL BACK DOOR UNIT REPLACE 2 WINDOW PANES CAULK ALL WINDOW

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	General air sealing (setup cost)	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Miscellaneous Su	Infiltration Reduction	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: 14014SO3790

Alt. Client ID: BEDFORD

Work Order (Bid Form)

Work Order Name: 14014SO3790

Report Run On: 10/6/2011

DOE Weatherization Assistant

Version 8.6.0

Page 2 of 5

Measure 2 Replace Heating [Electric]**Components****Inspected****Comment** INSTALL NEW HEATPUMP 82 PERCENT EFFICIENT OR GREATER
INSTALL NEW THERMOSTAT HEATING AND COOLING☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipme	Replacement elec furnace (not used)	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Replacement elec furnace (not used)	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total: **Sub Total:** **Field Notes:****Measure 3 Lighting [Kitcher][4]****Components** LT1**Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Lighting	Compact Fl. -7 Watt	Each	4	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Compact Fl. -7 Watt	Each	4	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total: **Sub Total:** **Field Notes:**

Client Name:

Client ID: 14014SO3790

Alt. Client ID: BEDFORD

Work Order (Bid Form)

Work Order Name: 14014SO3790

Report Run On: 10/6/2011

DOE Weatherization Assistant

Version 8.6.0

Page 3 of 5

Measure 4 Refrigerator Replacement**Components****Inspected****Comment** INSTALL ENERGY STAR 21 CU FT☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Refrigerators	-	Each	1					

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 5 Fix Improper Venting (Clothes Dryer)****Components****Inspected****Comment** Vent to exterior and cap as per 2.5.4 of SWFG (pages 2-17 and 2-18). VENT TO OUTSIDE WITH DAMPER☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Exterior Cap / Metal Flex / Clamps	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	3	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 14014SO3790

Alt. Client ID: BEDFORD

Work Order (Bid Form)

Work Order Name: 14014SO3790

Report Run On: 10/6/2011

DOE Weatherization Assistant

Version 8.6.0

Page 4 of 5

Measure 6 Smoke CARBONDetector is Needed **Components** **Inspected**
Comment INSTALL SMOKE CARBON DETECTOR ☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Smoke Carbondetector	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total: **Sub Total:**

Field Notes:

Work Order Grand Total: **Grand Total:**